



**Three-phase motor for 3 speeds**  
 with 2 separate windings, winding 1 in Dahlander connection  
 for speed 1, 2, winding 2 for star-delta starting

**Conn. diagram**  
**KP 0042**



All terminals to the pole-changing switch with built-in star/delta-starting, star connections for intermediate speed by pole-changing switch  
 Attention: During operating in low and intermediate speed, the delta of the high speed must be open!!!

			Datum	25.09.2005	
			Bearb	Kresse	
			Gepr		
			Norm		
					Zeichnungs-Nr. <b>KP 0042 e</b>
01			Elektromotorenwerk Wernigerode		
Zust.	Mitteilung	Datum	Name		