


Three-phase motor for 3 speeds

with 2 separate windings
winding 2 in Dahlander connection for speed 2, 3

Conn. diagram
KP 0043



For pole-changing switch connect all terminals with pole-changing switch
star connections for high speed by pole-changing switch

			Datum	09.11.2005
			Bearb	Kresse
			Gepr	
			Norm	
01				
Zust.	Mitteilung	Datum	Name	



Elektromotorenwerk
Wernigerode

Zeichnungs-Nr.
KP 0043 e